

Description	Part No.	Unit Cost
HP LaserJet 1010 series		
Fuser assembly (HP LaserJet 1010 series)	RM1-0655-000 (fuser)	£94.18
Paper pickup roller	RL1-0266-000 (roller)	£10.75
Paper separation pad assembly	RM1-0648-000 (pad)	£10.75
Transfer roller assembly	RM1-0658-000 (transfer roller)	£20.18
HP LaserJet 1010 / 1012 / 1015 series	Q2612A (toner)	£47.29
HP LaserJet 1100 series		
Fuser heater assembly (with brown film)	RG5-4590-000 (fuser spare)	£44.62
Fuser film	FILM-1100 (fuser spare)	£39.23
Lower fuser roller (orange rubber roller)	RF5-2823-000 (fuser spare)	£23.69
Fuser exit idle wheel (white)	RB2-4222-000 (fuser spare)	£2.13
Fuser exit idle wheel spring	RB1-7287-000 (spring)	£1.50
Transfer roller	RG5-4657-000 (transfer roller)	£25.73
Paper feed repair kit (HP LaserJet 1100) (contains 1x paper feed tyre, 1x separation pad and 2x sub-separation pads)	FKITLJ1100 (feed repair kit)	£17.08
Paper feed tyre	RB2-4026-000 (roller)	£6.25
Face down output roller	RF5-2830-000 (roller)	£12.00
Face up output roller	RF5-2822-000 (roller)	£17.13
Separation roller (2x black rollers on shaft)	RB2-3912-000 (roller)	£11.60
Paper separation pad	RF5-2886-000 (pad)	£5.00
Sub separation pad (left)	RF5-2820-000 (pad)	£4.25
Sub separation pad (right)	RF5-2821-000 (pad)	£4.25
Paper output assembly	RG5-4593-030 (paper path)	£27.27
Feed tyre shaft (holds paper feed tyre)	RB2-3930-000 (paper path)	£5.78
Gear assembly (clutch, paper feed)	RG5-4585-020 (paper path)	£7.83
Kick arm (applies pressure to paper stack when feeding)	RG5-4582-000 (paper path)	£17.13
Feed roller assembly	RG5-4581-000 (paper path)	£28.33
Rear paper support (transparent green paper support)	RG9-1332-000 (paper path)	£18.50
Front paper support (transparent green paper support)	RG9-1329-000 (paper path)	£20.18
Laser scanner assembly	RG5-4570-000 (scanner)	£81.30
HP LaserJet 1100 / 1100A / 3200 series	C4092A (toner)	£43.35
HP LaserJet 1150 series	Q2624A (toner)	£48.24
HP LaserJet 1000 / 1200 / 1220 / 3300 series	C7115A (toner)	£45.48
HP LaserJet 1000 / 1200 / 1220 / 3300 series	C7115X (high yield toner)	£50.05
HP LaserJet 1200/1300 series		
Fuser assembly (HP LaserJet 1200 series)	RG9-1494-040 (fuser)	£63.75
Fuser assembly (HP LaserJet 1300 series)	RM1-0536 (fuser)	£82.78
Transfer roller (HP LaserJet 1200 series)	RG9-1483-000 (transfer roller)	£21.55
Transfer roller (HP LaserJet 1300 series)	RM1-0550-000 (transfer roller)	£24.88
Paper feed repair kit (HP LaserJet 1200/1300 series) (contains 1x paper feed tyre and 1x separation pad)	FKITLJ1200 (feed repair kit)	£24.35
Paper feed tyre	RF0-1008-000 (roller)	£11.50
Paper separation pad	RF0-1014-000 (pad)	£15.08
Paper pickup roller shaft	RG0-1007-000 (paper path)	£8.50
Paper pickup assembly	RG0-1003-000 (paper path)	£47.73
Paper lifting plate	RG0-1006-000 (paper path)	£34.62
Output delivery roller assembly	RG0-1010-000 (paper path)	£27.07
Clutch for paper pickup roller	RY7-5081-000 (clutch)	£8.25
Paper tray (1200 series) excludes clear cover	RG0-1013-000 (tray)	£24.58
LaserJet scanner assembly	RG9-1486-000 (scanner)	£116.20
HP LaserJet 1000 / 1200 / 1220 / 3300 series	C7115A (toner)	£45.48
HP LaserJet 1000 / 1200 / 1220 / 3300 series	C7115X (high yield toner)	£50.05
HP LaserJet 1300 series	Q2613A (toner)	£48.70
HP LaserJet 1300 series	Q2613X (high yield toner)	£54.68
HP LaserJet 2100/2200 series		
Maintenance kit (HP LaserJet 2100, 2100M) (contains fuser, transfer roller, cassette pickup tyre and 1x separation pad)	MKIT2100 (maintenance kit)	£110.95

Description	Part No.	Unit Cost
Maintenance kit (HP LaserJet 2200D, 2200DTN) (contains fuser, transfer roller, cassette pickup tyre and 1x separation pad)	MKIT2200 (maintenance kit)	£128.25
Fuser assembly (HP LaserJet 2100 series)	RG5-4133-000 (fuser)	£86.08
Fuser assembly (HP LaserJet 2200 series)	RG5-5569-000 (fuser)	£91.27
Fuser film (HP LaserJet 2100)	FILM-2100 (fuser spare)	£32.25
Fuser film (HP LaserJet 2200)	FILM-2200 (fuser spare)	£36.92
Lower fuser roller (HP LaserJet 2100 series)	RF5-2601-000 (fuser spare)	£23.64
Lower fuser roller (HP LaserJet 2200 series)	RB2-6369-000 (fuser spare)	£43.53
Transfer roller (HP LaserJet 2100)	RG5-4164-000 (transfer roller)	£22.25
Transfer roller (HP LaserJet 2200)	RG5-5581-000 (transfer roller)	£29.17
Paper feed repair kit (HP LaserJet 2100, 2100M, 2200, 2200D, 2200DN - single paper tray models) (contains MP tray feed tyre, MP tray separation pad, cassette pickup tyre and cassette separation pad)	FKITLJ2100 (feed repair kit)	£31.67
Paper feed repair kit (HP LaserJet 2100TN, 2200DT, 2200DTN - dual paper tray models) (contains MP tray feed tyre, MP tray separation pad, 2x cassette pickup tyres and 2x cassette separation pads)	FKITLJ2100T (feed repair kit)	£37.54
Paper pick up roller (tray 1)	RB2-2900-000 (roller)	£17.75
Paper pick up roller (tray 2) main cassette feed tyre	RB2-2891-000 (roller)	£15.00
Delivery rollers (lower) 4x used 2100/2200	RB2-2849-000 (roller)	£2.13
Exit roller	RF5-2604-000 (roller)	£10.75
Paper separation pad (tray 1)	RB2-6348-000 (pad)	£17.25
Paper separation pad (tray 2)	RB9-0695-000 (pad)	£21.68
Paper separation pad (on metal plate) 500 sheet cassette (HP LaserJet 2200)	RB2-3007-000 (pad)	£2.23
Paper separation pad (on cassette arm) 500 sheet cassette (HP LaserJet 2200)	RB2-6474-000 (pad)	£21.25
Delivery roller assembly 2100 (4x used)	RG5-4119-000 (paper path)	£8.75
MP Tray pickup roller assembly 2100/2200	RG5-4128-000 (paper path)	£27.63
Tray 2 pickup assembly 2100	RG5-4127-000 (paper path)	£47.43
Drive assembly (gear assembly on right hand side)	RG5-4131-000 (paper path)	£63.38
Drive assembly, tray 3	RG5-4391-000 (paper path)	£44.77
Delivery guide assembly	RG5-4141-000 (paper path)	£ call
250 Sheet paper tray, tray 2/3	R98-1003-000 (tray)	£66.88
MP Tray assembly	RG5-4126-000 (tray)	£24.75
Cover MP tray 2100/2200	RG5-4121-000 (tray)	£45.79
Transport belt kit 2100	RY7-5053-000 (belt)	£26.50
Paper feed belt (smallest)	RB2-6270-000 (belt)	£4.50
Paper feed belt (wide middle belt)	RB2-6272-000 (belt)	£17.13
Paper feed belt (long narrow rear belt)	RB2-6273-000 (belt)	£17.13
Laser scanner assembly 2100	RG5-4172-000 (scanner)	£113.06
Laser scanner assembly 2200	RG5-5591-000 (scanner)	£129.11
HP LaserJet 2100 / 2200 series	C4096A (toner)	£62.36
HP LaserJet 2300 series		
Maintenance kit (contains fuser, transfer roller, cassette pickup tyre and cassette separation pad)	MKIT2300 (maintenance kit)	£ call
Fuser assembly (HP LaserJet 2300 series)	RM1-0355-000 (fuser)	£153.42
Fusing roller assembly	RM1-0357-000 (fuser spare)	£118.23
Paper feed repair kit	FKITLJ2300 (feed repair kit)	£ call
Paper feed guide roller	RB2-2892-000 (roller)	£17.00
Paper feed roller for sheet feeder	RB2-3484-000 (roller)	£6.25
Top output bin roller	RB2-6277-000 (roller)	£4.25
Paper pickup roller (tray 2 and tray 3)	RB2-6304-000 (roller)	£28.00
Paper feed roller (tray 2)	RG5-5555-000 (roller)	£51.85
Paper feed roller	RC1-0920-000 (roller)	£2.13
MP/Tray 1 pickup roller	RC1-0945-000 (roller)	£6.25
Face down output roller	RM1-0371-000 (roller)	£4.25
Paper separation pad	RB2-3007-000 (pad)	£2.00
Paper separation pad (tray 1)	RC1-0939-000 (pad)	£10.50
Paper feed roller assembly	RG5-4394-000 (paper path)	£40.54

Description	Part No.	Unit Cost
Paper separation pad assembly	RB2-9960-000 (paper path)	£12.63
Paper pickup assembly	RM1-0332-000 (paper path)	£53.25
Laser scanner assembly 2300	RM1-0313-000 (scanner)	£122.72
HP LaserJet 2300 series	Q2610A (toner)	£73.51
HP LaserJet 4000/4050 series		
Maintenance kit (HP LaserJet 4000, 4000N, 4050, 4050N - single paper tray models) (contains fuser, transfer roller, 2x feed tyres, 4x half moon tyres and MP tyre)	MKIT4000 (maintenance kit)	£123.80
Fuser assembly (HP LaserJet 4000 / HP LaserJet 4050 series)	RG5-2662-000 (fuser)	£98.48
Fuser heater assembly (220V)	RG5-4291-100 (fuser spare)	£48.00
Fuser film	FILM-4000 (fuser spare)	£32.25
Lower fuser roller	RB9-0684-000 (fuser spare)	£26.36
Transfer roller	RG5-4283-000 (transfer roller)	£23.25
Paper feed repair kit (HP LaserJet 4000, 4000N, 4050, 4050N - single paper tray models) (contains MP feed tyre, MP separation pad, 2x feed/separation rollers, 4x half moon tyres and 1x torque limiter clutch)	FKITLJ4000 (feed repair kit)	£32.08
Paper feed repair kit (HP LaserJet 4000T, 4000TN, 4050T, 4050TN - dual paper tray models) (contains MP feed tyre, MP separation pad, 4x feed/separation rollers, 8x half moon tyres and 2x torque limiter clutches)	FKITLJ4000T (feed repair kit)	£41.08
Paper feed / separation tyre (tray 2, 3 and 4 - grey with blue core) (old Part No. RF5-2490-000)	RF5-1885-000 (roller)	£4.50
Paper pickup tyre (tray 2, 3 and 4 - half moon, 4x off required)	RB1-8865-000 (roller)	£4.28
Paper pickup tyre (multi-purpose tray)	RG5-3718-000 (roller)	£12.13
Spring (attached to paper feed shaft)	RS5-2632-000 (spring)	£1.00
Paper pickup tyre assembly (4x half moon tyres on shaft)	RF5-2484-000 (paper path)	£16.50
Paper separation assembly (multi-purpose tray)	RG5-5281-000 (paper path)	£4.00
Torque limiter (friction coupling located on tyre RF5-2490-000, eliminates jamming from cassette)	RB1-8974-000 (paper path)	£16.38
Coupler (paper feed shaft drive coupler)	RB1-8877-000 (paper path)	£4.00
Tray 1 pickup assembly (mp tray)	RG5-2655-000 (paper path)	£71.75
Registration Assembly	RG5-2652-000 (paper path)	£31.67
Delivery Assembly	RG5-2648-000 (paper path)	£54.55
MP tray (paper support tray with adjustable guides)	RG5-2656-000 (paper path)	£26.33
MP tray paper sensor lever arm	RB1-8787-000 (paper path)	£2.95
Sensor lever cover (holds tray 1 paper detection switch)	RB1-8788-020 (paper path)	£6.00
Paper sensing arm (tray 2)	RB1-8879-000 (paper path)	£4.45
Paper sensing arm (tray 3)	RB1-8910-000 (paper path)	£4.60
Paper exit arm and flag	RG5-2650-000 (paper path)	£11.00
Drive assembly	RG5-2653-000 (paper path)	£57.09
Laser scanner assembly LaserJet 4000/4050	RG5-2641-000 (scanner)	£99.11
HP LaserJet 4000 / 4050 series	C4127A (toner)	£62.42
HP LaserJet 4000 / 4050 series	C4127X (high yield toner)	£77.10
HP LaserJet 4100 series		
Maintenance kit (HP LaserJet 4100, 4100N, 4100TN, 4100DTN) (contains fuser, transfer roller, 4x feed tyres, 8x half moon tyres and MP tyre)	MKIT4100 (maintenance kit)	£160.51
Fuser assembly (HP LaserJet 4100 series)	RG5-5064-180 (fuser)	£121.27
Fuser film	FILM-4100 (fuser spare)	£36.92
Lower fuser roller	RB2-4937-000 (fuser spare)	£41.54
Transfer roller	RG5-5295-000 (transfer roller)	£33.28
Paper feed repair kit (HP LaserJet 4100, 4100N - single paper tray models) (contains MP feed tyre, MP separation pad, 2x feed/separation rollers, 4x quarter moon tyres and 1x torque limiter clutch)	FKITLJ4100 (feed repair kit)	£41.08
Paper feed repair kit (HP LaserJet 4100T, 4100TN - dual paper tray models) (contains MP feed tyre, MP separation pad, 4x feed/separation rollers, 8x quarter moon tyres and 2x torque limiter clutch)	FKITLJ4100T (feed repair kit)	£47.01
Paper feed / separation tyre (tray 2, 3 and 4 - grey with blue core)	RF5-3114-000 (roller)	£10.50
Paper pickup tyre (tray 2, 3 and 4 - half moon, 4x off required)	RB1-8957-000 (roller)	£4.28
Paper pickup tyre (multi-purpose tray)	RG5-3718-000 (roller)	£9.63
Paper separation assembly (multi-purpose tray)	RG5-3086-000 (paper path)	£24.82

Description	Part No.	Unit Cost
Spring (attached to paper feed shaft)	RS5-2632-000 (spring)	£1.00
Coupler (paper feed shaft drive coupler)	RB1-8877-000 (paper path)	£3.75
Paper pickup drive assembly T2 4100/N	RG5-5277-000 (paper path)	£84.94
Lower paper pickup drive assembly T4 (optional tray) 4100 series	RG5-5293-000 (paper path)	£98.61
Torque limiter (friction coupling located on tyre, eliminates jamming from cassette)	RB1-8974-000 (paper path)	£12.13
Tray 1 pickup assembly (mp tray)	RG5-5084-000 (paper path)	£63.51
Registration Assembly	RG5-5085-000 (paper path)	£50.93
Delivery Assembly	RG5-5094-000 (paper path)	£56.31
MP tray paper sensor lever arm	RB1-8787-000 (paper path)	£2.95
Sensor lever cover (holds tray 1 paper detection switch)	RB1-8788-020 (paper path)	£6.00
Paper sensing arm (tray 2/3/4)	RB1-8879-000 (paper path)	£4.45
Paper exit arm and flag assembly	RG5-5093-000 (paper path)	£16.15
MP tray (paper support tray with adjustable guides)	RG5-2656-000 (tray)	£26.33
Print drive assembly	RG5-5087-000 (mechanical)	£49.47
Laser scanner assembly LaserJet 4100	RG5-5100-000 (scanner)	£211.65
HP LaserJet 4100 series	C8061A (toner)	£61.08
HP LaserJet 4100 series	C8061X (high yield toner)	£77.23
HP LaserJet 4200/4300 series		
Maintenance kit (HP LaserJet 4200) c2k	MKIT4200 (maintenance kit)	£171.47
Maintenance kit (HP LaserJet 4300) c2k	MKIT4300 (maintenance kit)	£201.00
Fuser assembly (HP LaserJet 4200 series)	RM1-0014-000 (fuser)	£181.01
Fuser assembly (HP LaserJet 4300 series)	RM1-0102-000 (fuser)	£231.14
Fuser Film 4200	FILM-4200 (fuser spare)	£ call
Fuser Film 4300	FILM-4300 (fuser spare)	£ call
Fuser Roller 4200	RM1-0016-000 (fuser spare)	£ call
Fuser Roller 4300	RM1-0104-000 (fuser spare)	£ call
Fuser unit pressure roller 4200/4300	RC1-0070-000 (fuser spare)	£ call
Transfer roller assembly 4200/4300	RM1-0699-000 (transfer roller)	£19.00
Paper feed repair kit, LaserJet 4200 series (single cassette models 4200/N)	FKIT4200 (feed repair kit)	£46.00
Paper feed repair kit, LaserJet 4200 series (twin cassette models 4200DTN)	FKIT4200T (feed repair kit)	£ call
Paper feed repair kit, LaserJet 4300 series (single cassette models 4300/N)	FKIT4300 (feed repair kit)	£46.00
Paper feed repair kit, LaserJet 4300 series (twin cassette models 4300DTN)	FKIT4300T (feed repair kit)	£ call
Tray 1 pickup roller 4200/4300	RL1-0019-000 (roller)	£16.75
Tray 2 pickup roller 4200/4300	RM1-0036-000 (roller)	£8.75
Paper pick up roller for tray 2 4200/4300	RM1-0037-000 (roller)	£8.75
Face down output roller 4200/4300	RM1-0371-000 (roller)	£4.25
Tray 1 paper separation pad 4200/4300	RL1-0007-000 (pad)	£4.25
Paper feed assembly clutch 4200/4300 (CL101)	RH7-5358-000 (clutch)	£26.18
Front cover - Drop down tray 1 4200	RM1-0050-000 (tray)	£12.75
Paper size sensor flag 4200/4300	RC1-0161-000 (sensor)	£2.13
Paper sensing flag for tray 2 4200/4300	RC1-0209-000 (sensor)	£2.13
Paper feed flag for tray 1 4200/4300	RC1-0060-000 (flag)	£4.25
Torsion spring 4200/4300	RC1-0061-000 (spring)	£2.13
Torsion spring for lifter drive assembly 4200/4300	RC1-0198-000 (spring)	£2.13
Paper feed belt assembly 4200/4300	RM1-0025-000 (paper path)	£20.18
Paper pickup assembly for tray 1 4200	RM1-0034-000 (paper path)	£57.01
Torque limiter 4200	RC1-0335-000 (paper path)	£20.91
Paper pickup drive assembly 4300	RM1-0056-000 (paper path)	£28.50
Registration roller assembly 4200/4300	RM1-0011-000 (paper path)	£52.60
Paper feed roller assembly 4200/4300	RM1-0012-000 (paper path)	£60.13
Paper delivery assembly 4200/4300	RM1-0026-000 (paper path)	£45.00
Front cover stop arm 4200/4300	RC1-0714-000 (paper path)	£2.13
Bushing - Right side of paper pickup drive assembly 4200/4300	RC1-0206-000 (paper path)	£2.13

Description	Part No.	Unit Cost
Paper pickup arm holder for roller shaft 4200/4300	RC1-0212-000 (paper path)	£2.13
Paper pickup arm for tray 2 4200/4300	RC1-0211-000 (paper path)	£2.13
Lifter driver assembly 4200/4300	RM1-0287-020 (paper path)	£47.86
Paper level sensor gear assembly 4200/4300	RM1-0286-000 (paper path)	£10.50
Tray lifter drive assembly	RM1-0208-000 (paper path)	£19.00
HP LaserJet 4200 series	Q1338A (toner)	£91.49
HP LaserJet 4300 series	Q1339A (toner)	£122.03
HP LaserJet 5000 series		
Maintenance kit (HP LaserJet 5000) (contains fuser, transfer roller, 2x tyres, 1x separation pad and 2x MP sub-separation pads) C4110-67902	MKIT5000 (maintenance kit)	£206.33
Fuser assembly (HP LaserJet 5000 series)	RG5-5460-000 (fuser)	£156.96
Fuser film	FILM-5000 (fuser spare)	£43.08
Fuser heater assembly (heater and film)	RG5-5459-000 (fuser spare)	£88.52
Lower fuser silicon roller	RB2-1919-000 (fuser spare)	£26.73
Transfer roller	RG5-3579-000 (transfer roller)	£45.57
Paper feed repair kit (HP LaserJet 5000) (contains MP tray feed tyre, MP tray separation pad, cassette feed tyre and cassette separation pad)	FKITLJ5000 (feed repair kit)	£34.37
Paper feed repair kit (HP LaserJet 5000TN) (contains MP tray feed tyre, MP tray separation pad, cassette feed tyre, cassette separation pad, 2x tray 3 feed/separation rollers and 4x tray 3 half moon tyres)	FKITLJ5000T (feed repair kit)	£47.15
Paper pickup roller (tray 2)	RB2-1821-000 (roller)	£15.00
Paper pickup tyre, tray 1	RB2-1820-000 (roller)	£10.50
Paper separation roller, tray 3 (grey core) 2 used	RF5-2634-000 (roller)	£15.10
Paper separation pad (tray 2)	RG9-1485-000 (pad)	£22.50
Sub separation pad, MP tray (small pad located near separation pad) 2x off required	RF5-2399-000 (pad)	£4.30
Separation pad, tray 1	RF5-2400-000 (pad)	£17.30
Torque limiter	RB1-8974-000 (paper path)	£16.38
Delivery assembly	RG5-3542-000 (paper path)	£37.08
Delivery roller (upper, final delivery roller shaft)	RB2-1984-000 (paper path)	£0.00
Laser scanner assembly	RG5-3603-000 (scanner)	£384.05
HP LaserJet 5000 / 5100 series	C4129X (high yield toner)	£97.03
HP LaserJet 5100 series		
Maintenance kit (HP LaserJet 5100) (contains fuser, transfer roller, 2x tyres, 1x separation pad and 2x MP sub-separation pads) C1860-67903	MKIT5100 (maintenance kit)	£206.33
Fuser assembly (HP LaserJet 5100 series)	RG5-7061-080 (fuser)	£156.20
Fuser film	FILM-5100 (fuser spare)	£43.08
Transfer roller	RG9-1542-000 (transfer roller)	£43.54
Paper feed repair kit (HP LaserJet 5000/5100) (contains MP tray feed tyre, MP tray separation pad, cassette feed tyre and cassette separation pad)	FKITLJ5000 (feed repair kit)	£34.37
Paper feed repair kit (HP LaserJet 5100/5100TN) (contains MP tray feed tyre, MP tray separation pad, cassette feed tyre, cassette separation pad, 2x tray 3 feed/separation rollers and 4x tray 3 half moon tyres)	FKITLJ5000T (feed repair kit)	£47.15
Paper pickup roller (tray 1)	RB2-1820-020 (roller)	£10.50
Feed roller - 250 sheet feeder assembly feed roller	RB1-7499-000 (roller)	£23.27
Paper separation roller, tray 3 (grey core) 2 used	RF5-2634-000 (roller)	£15.10
Lower delivery roller	RB1-6251-000 (roller)	£2.13
Paper pickup roller - 250 sheet tray - tray 2	RB2-1821-000 (roller)	£15.00
Lower output delivery roller - shaft with four rollers	RB2-1985-000 (roller)	£16.38
Roller - Upper roller of face-down roller guide - 4 used	RB2-1998-000 (roller)	£2.13
Face down guide roller	RG9-1337-000 (roller)	£16.75
Upper delivery roller - paper output	RG5-3542-090 (roller)	£37.08
Paper separation pad (tray 1)	RF9-4119-000 (pad)	£18.13
Pad assembly	RF5-4117-000 (pad)	£6.05
Tray 1 pickup roller gear	RB1-6130-000 (mechanical)	£16.00
Tray 2 pickup roller shaft drive gear	RS5-0695-000 (mechanical)	£16.00
Pickup roller assembly	RG5-3519-000 (paper path)	£32.35
Tray 2 paper pickup roller assembly	RG5-3521-000 (paper path)	£34.46
Pickup roller assembly for optional 250 sheet tray	RG5-3644-020 (paper path)	£31.50

Description	Part No.	Unit Cost
Registration roller assembly	RG5-4916-000 (paper path)	£41.69
Paper feed roller assembly	RG5-7084-000 (paper path)	£49.86
HP LaserJet 5000 / 5100 series	C4129X (high yield toner)	£97.03
HP LaserJet 5Si/8000 series		
Maintenance kit (HP LaserJet 5Si / HP LaserJet 8000) (contains fuser, transfer roller and 7x tyres)	MKIT5SI (maintenance kit)	£172.15
Fuser assembly (HP LaserJet 5Si / HP LaserJet 8000 series)	RG5-4448-050 (fuser)	£150.63
Heat roller	RB1-6622-000 (fuser spare)	£20.36
Lower fuser roller	RB1-6623-000 (fuser spare)	£36.15
Heat roller bushing (grey bearing insert)	FB1-6823-000 (fuser spare)	£1.50
Heat lamp 220V 500W #1	RH7-4074-000 (fuser spare)	£16.75
Heat lamp 220V 500W #2	RH7-4075-000 (fuser spare)	£20.36
Transfer roller	RF5-1412-000 (transfer roller)	£24.55
Transfer roller assembly	RG5-1887-000 (mechanical)	£29.17
Paper feed repair kit (HP LaserJet 5Si, 5SiMX, 8000) (contains 4x pickup rollers, 2x separation rollers, MP roller, MP separation pad and 4x registration tyres)	FKITLJ5SI (feed repair kit)	£47.71
Paper pickup roller, tray 2 & tray 3 (blue core)	RF5-1426-000 (roller)	£3.00
Paper separation roller, tray 2 & tray 3 (black core)	RF5-1427-000 (roller)	£3.00
MP tray pickup tyre (tray 1)	RB1-6730-000 (roller)	£6.50
MP tray separation pad (tray 1)	RF5-1455-000 (pad)	£8.00
Torque limiter	RB1-6588-000 (paper path)	£15.15
Tray 2/3 registration roller tyre assembly (4 black rubber tyres on shaft)	RZ9-1022-030 (paper path)	£81.16
Tray 2/3 pickup assembly	RG5-1852-000 (paper path)	£201.77
Laser scanner assembly	RG5-1895-000 (scanner)	£ call
HP LaserJet 5Si / 8000 / Mopier 240 series	C3909A (toner)	£105.25
HP LaserJet 5Si / 8000 / Mopier 240 series	C3909X (high yield toner)	£114.57
HP LaserJet 8100/8150 series		
Maintenance kit (HP LaserJet 8100 / HP LaserJet 8150) (contains fuser, transfer roller and 7x tyres)	MKIT8100 (maintenance kit)	£218.99
Fuser assembly (HP LaserJet 8100 / HP LaserJet 8150 series)	RG5-4319-000 (fuser)	£200.00
Heat roller	RB2-3521-000 (fuser spare)	£38.18
Lower fuser roller	RB2-3523-000 (fuser spare)	£38.46
Paper feed repair kit (HP LaserJet 8100, 8150) (contains 4x pickup rollers, 2x separation rollers, MP roller, MP separation pad and 4x registration tyres)	FKITLJ8100 (feed repair kit)	£50.72
Paper pickup roller (tray 2 and 3 - blue core) Old part number RF5-1834-000	RF5-1426-000 (roller)	£3.00
Paper pickup roller	RF5-2708-000 (roller)	£8.65
Paper separation roller (tray 2 and 3 - black core)	RF5-1427-000 (roller)	£3.00
MP tray pickup tyre	RB1-9526-000 (roller)	£6.50
MP tray separation pad	RF5-2703-000 (pad)	£10.50
Tray 2/3 pickup assembly	RG5-4334-000 (paper path)	£203.90
Laser scanner assembly	RG5-4344-000 (scanner)	£ call
HP LaserJet 8100 / 8150 series	C4182X (high yield toner)	£115.00
HP LaserJet 9000 series		
Maintenance kit (HP LaserJet 9000)	MKIT9000 (maintenance kit)	£354.43
Fuser assembly (HP LaserJet 9000 series)	C8519-69003 (fuser)	£ call
Transfer roller	RF5-3319-000 (transfer roller)	£58.96
Paper feed repair kit (HP LaserJet 9000) For printers fitted with tray 1 and tray 4 feeders (contains 1x tray 1 pickup tyre, 2x tray 1 separation tyres, 2x tray 2/3 pickup tyres, 7x tray 2/3 separation tyres)	FKITLJ9000 (feed repair kit)	£62.96
Paper feed / separation roller (tray 2 & 3) 4x used	RF5-3338-000 (roller)	£10.75
Paper pickup roller (tray 1)	RF5-3403-000 (roller)	£19.00
Paper separation roller (tray 1) 2x used	RF5-3404-000 (roller)	£21.09
Paper pickup roller (tray 2 & 3) 2x used	RF5-3340-000 (roller)	£20.50
Torque limiter (tray 2 & 3)	RB2-5759-000 (paper path)	£20.18
Registration roller assembly	C8519-69012 (paper path)	£205.57
Paper pickup assembly	C8519-69025 (paper path)	£ call

Description	Part No.	Unit Cost
HP LaserJet 9000 series	C8543X (high yield toner)	£169.27
HP LaserJet II/III series		
Fuser assembly (HP LaserJet II / III series) Discontinued item. Exchange unit possible - call for details.	RG1-0940-450 (fuser)	£ n/a
Heat roller	RA1-3968-000 (fuser spare)	£8.75
Fuser cleaning wand	RG1-0966-030 (fuser spare)	£2.25
Paper feed repair kit (HP LaserJet II / III) Discontinued item. Use RA1-3851-000 (main pickup roller) and RF1-1145-000 (separation pad) to overcome paper pickup problems.	FKITLJ3 (feed repair kit)	£ n/a
Main paper pickup roller	RA1-3851-000 (roller)	£5.00
Paper separation pad	RF1-1145-000 (pad)	£8.78
Upper heat extract fan (new style)	RH7-1122-000 (fan)	£14.88
Ozone filter	RF1-2130-000 (filter)	£8.63
HP LaserJet II / III series	92295A (toner)	£64.83
HP LaserJet IIP/IIIP series		
Fuser assembly (HP LaserJet IIP / IIIP series) Discontinued item. Exchange unit possible - call for details.	RG1-1789-220 (fuser)	£ n/a
Heat lamp	RF1-3304-000 (fuser spare)	£20.00
Paper feed repair kit (HP LaserJet IIP, IIP+, IIIP) (contains 2x tyres, 1x separation pad, delivery roller assembly and drum drive gear assembly)	FKITLJ3P (feed repair kit)	£32.85
Paper pickup tyre (2x off required)	RA1-7573-060 (roller)	£4.25
Paper separation pad	RG1-1912-000 (pad)	£7.50
Delivery roller assembly	RG1-1791-070 (paper path)	£25.00
Scanner motor PCB	RG1-1771-030 (pcb)	£37.69
Drum drive gear assembly	RG1-1777-000 (gear)	£14.63
HP LaserJet IIP / IIP+ / IIIP series	92275A (toner)	£62.81
HP LaserJet IIISi/4Si series		
Maintenance kit (HP LaserJet IIISi / HP LaserJet 4Si) (contains fuser, transfer roller, clip and 6x feed tyres)	MKIT4Si (maintenance kit)	£182.28
Fuser assembly (HP LaserJet IIISi / HP LaserJet 4Si series)	RG5-0047-000 (fuser)	£181.01
Transfer roller assembly	RG5-0141-000 (transfer roller)	£20.50
Paper feed repair kit (HP LaserJet IIISi, 4Si, MX) (contains 6x tyres and registration roller assembly)	FKITLJ4Si (feed repair kit)	£45.85
Main paper pickup / separation roller (blue core)	RF5-0041-000 (roller)	£2.13
HP LaserJet IIISi / 4Si series	92291A (toner)	£77.90
HP LaserJet IIISi / 4Si series	92291X (high yield toner)	£78.44
HP LaserJet 4L/4P series		
Fuser assembly (HP LaserJet 4L / HP LaserJet 4P series)	RG5-0677-000 (fuser)	£93.67
Fuser film	FILM-HP4L (fuser spare)	£36.92
Fuser lower press roller	RB1-3100-000 (fuser spare)	£18.40
Transfer roller assembly	RF5-0596-000 (transfer roller)	£24.08
Paper pickup tyre	RB1-3368-000 (roller)	£8.13
Exit roller assembly (4x off rollers on shaft)	RG5-0683-000 (paper path)	£20.82
Drive motor with nylon gear	RG5-0765-000 (motor)	£26.18
Laser scanner assembly	RG5-0662-000 (scanner)	£ call
HP LaserJet 4L / 4P series	92274A (toner)	£56.42
HP LaserJet 4/4+/5 series		
Maintenance kit (HP LaserJet 4, 4M) (contains fuser, transfer roller, cassette feed tyre and MP tyre)	MKIT4 (maintenance kit)	£91.14
Maintenance kit (HP LaserJet 4+, 4M+) (contains fuser, transfer roller, cassette feed tyre and MP tyre)	MKIT4PLUS (maintenance kit)	£91.14
Maintenance kit (HP LaserJet 5, 5M, 5N) (contains fuser, transfer roller, cassette feed tyre and MP tyre)	MKIT5 (maintenance kit)	£96.20
Fuser assembly (HP LaserJet 4, 4M series)	RG5-0455-000 (fuser)	£86.08
Fuser assembly (HP LaserJet 4+, 4M+, 5, 5M, 5N series)	RG5-0880-000 (fuser)	£86.08
Upper fuser roller (HP LaserJet 4+, 4M+, 5, 5M, 5N series)	RB1-3516-000 (fuser spare)	£13.50
Lower fuser roller (HP LaserJet 4+, 4M+, 5, 5M, 5N series)	RB1-3517-000 (fuser spare)	£25.45
Fuser heat lamp (220V)	RH7-4049-000 (fuser spare)	£17.50
Transfer roller	RF5-0349-000 (transfer roller)	£24.00

Description	Part No.	Unit Cost
Paper feed repair kit (HP LaserJet 4, 4M, 4+, 4M+) (contains 2x tyres, 1x separation pad, upper and lower exit rollers)	FKITLJ4 (feed repair kit)	£25.45
Paper feed repair kit (HP LaserJet 5, 5M, 5N) (contains 2x tyres, 1x separation pad, upper and lower exit rollers)	FKITLJ5 (feed repair kit)	£27.67
Paper pickup roller - cassette tyre (HP LaserJet 4, 4M)	RB1-2126-000 (roller)	£3.00
Paper pickup roller - cassette tyre (HP LaserJet 4+, 4M+, 5, 5M, 5N)	RB1-3477-000 (roller)	£4.50
Paper pickup roller - cassette tyre (HP LaserJet 5, 5M, 5N)	RB1-7911-000 (roller)	£9.50
Paper pickup tyre (multi-purpose tray)	RB1-2127-000 (roller)	£3.00
Upper delivery roller	RF5-1076-000 (roller)	£9.88
Lower delivery roller	RF5-1077-000 (roller)	£9.88
Paper separation pad (multi-purpose tray)	RF5-0343-000 (pad)	£4.20
Paper pickup assembly unit (LaserJet 4)	RG5-0451-000 (paper path)	£ call
Paper pickup assembly unit (LaserJet 4+/4M+)	RG5-0877-000 (paper path)	£ call
Paper pickup assembly unit (LaserJet 5/5M/5N)	RG5-2195-000 (paper path)	£ call
Output delivery roller assembly, LJ4/4+/4M+	RG5-0886-000 (paper path)	£37.85
Output delivery roller assembly, LJ5/5M/5N	RG5-1425-030 (paper path)	£54.55
Drive gear assembly, LaserJet 4 (cluster of gears from main motor/drives fuser)	RG5-0457-000 (mechanical)	£23.09
Drive gear assembly, LaserJet 4+/4M+/5/5M/5N (cluster of gears from main motor/drives fuser)	RG5-0876-060 (mechanical)	£20.18
HP LaserJet 4 / 4M / 4+ / 4M+ / 5 series	92298A (toner)	£59.95
HP LaserJet 4 / 4M / 4+ / 4M+ / 5 series	92298X (high yield toner)	£61.79
HP LaserJet 4V series		
Maintenance kit (HP LaserJet 4V) (contains fuser, transfer roller, MP tyre, cassette tyre shaft and clutch)	MKIT4V (maintenance kit)	£211.52
Fuser assembly (HP LaserJet 4V series)	RG5-1558-000 (fuser)	£169.75
Lower fuser roller (black rubber roller)	RB1-5472-000 (fuser spare)	£38.14
Heat roller	RB1-5495-000 (fuser spare)	£19.09
Transfer roller assembly	RG5-1410-000 (transfer roller)	£28.02
Paper feed repair kit (HP LaserJet 4V, 4MV) (contains cassette tyre shaft and clutch, MP tyre, MP separation pad and upper exit rollers)	FKITLJ4V (feed repair kit)	£41.38
Paper pickup tyre (multi-purpose tray)	RB1-1411-000 (roller)	£11.25
Paper separation pad (multi-purpose tray)	RF5-0320-000 (pad)	£12.13
Paper pickup roller assembly inc. clutch (cassette)	RG5-1391-000 (paper path)	£32.31
Face down delivery roller assembly	RG5-0198-000 (paper path)	£25.45
MP front tray assembly	RG5-1562-000 (paper path)	£52.49
HP LaserJet 4V / 4MV series	C3900A (toner)	£87.47
HP LaserJet 5L/6L series		
Fuser heater assembly (HP LaserJet 5L)	RG5-1965-000 (fuser spare)	£40.00
Fuser heater assembly (HP LaserJet 6L)	RG5-3463-000 (fuser spare)	£40.00
Fuser heater assembly (HP LaserJet 3100, 3150)	RG5-4681-000 (fuser spare)	£58.44
Fuser film (HP LaserJet 5L, 6L, 3100, 3150)	FILM-5L (fuser spare)	£28.33
Lower fuser roller (HP LaserJet 5L)	RF5-1516-000 (fuser spare)	£21.82
Lower fuser roller (HP LaserJet 6L, 3100, 3150)	RF5-2364-000 (fuser spare)	£21.82
Transfer roller	RF5-1534-000 (transfer roller)	£17.50
Paper feed repair kit (HP LaserJet 5L, 6L, 3100, 3150) (contains feed tyre and shaft, separation pad kit, pressure spring and clip)	FKITLJ6L (feed repair kit)	£20.64
Paper feed separation pad	RB2-6221-000 (pad)	£8.75
Paper feed separation kit	RY7-5008-000 (pad)	£18.75
Paper feed tyre assembly	RG5-1951-000 (paper path)	£17.13
Feed tyre clutch (located on end of feed tyre shaft)	RB1-7197-000 (clutch)	£8.00
Feed assembly, idler roller only (idler roller located within feed assembly)	RB1-7226-000 (paper path)	£5.05
HP LaserJet 5L / 6L / 3100 / 3150 series	C3906A (toner)	£44.89
HP LaserJet 5P/6P series		
Maintenance kit (HP LaserJet 6P, 6MP) (contains fuser, transfer roller, cassette tyre and MP tyre)	MKIT6P (maintenance kit)	£98.99
Fuser assembly (HP LaserJet 5P, 5MP series)	RG5-1701-000 (fuser)	£109.37
Fuser assembly (HP LaserJet 6P, 6MP series)	RG5-2801-000 (fuser)	£75.32
Fuser film (5P, 5MP, 6P, 6MP)	FILM-5P (fuser spare)	£28.33
Lower fuser roller (HP LaserJet 5P, 5MP)	RB1-5910-000 (fuser spare)	£30.68

Description	Part No.	Unit Cost
Lower fuser roller (HP LaserJet 6P, 6MP)	RB1-9179-000 (fuser spare)	£23.64
Transfer roller (HP LaserJet 5P, 5MP)	RF5-1287-000 (transfer roller)	£25.00
Transfer roller (HP LaserJet 6P, 6MP)	RG5-0596-000 (transfer roller)	£25.00
Paper feed repair kit (HP LaserJet 5P, 5MP, 6P, 6MP) (contains 2x tyres, 1x separation pad and upper exit roller shaft)	FKITLJ6P (feed repair kit)	£20.04
Paper pickup tyre (main cassette)	RB1-6332-000 (roller)	£9.00
Paper pickup tyre (multi-purpose tray)	RB1-2127-000 (roller)	£3.00
Paper feed separation pad (multi-purpose tray)	RF5-0343-000 (pad)	£4.33
Paper pickup tyre assembly (HP LaserJet 5P, 5MP)	RG5-1692-000 (paper path)	£43.75
Paper pickup tyre assembly (HP LaserJet 6P, 6MP)	RG5-2796-000 (paper path)	£45.71
Exit roller assembly (4x off rollers on shaft)	RG5-0683-000 (paper path)	£20.82
HP LaserJet 5P / 5MP / 6P / 6MP series	C3903A (toner)	£51.37
HP Colour LaserJet 1500/2500 series		
Fuser assembly (HP Colour LaserJet 1500 / HP Colour LaserJet 2500 series)	RG5-6913-000 (fuser)	£189.24
Transfer roller assembly	RF5-4040-000 (transfer roller)	£24.55
Paper feed repair kit	FKITLJ2500 (feed repair kit)	£ call
Face down, upper roller	RB2-9908-000 (roller)	£2.13
Paper pickup roller (D-shape - multi-purpose tray)	RB3-0160-000 (roller)	£8.25
Guide roller	RB2-2892-000 (roller)	£17.00
Paper feed separation pad assembly (multi-purpose tray)	RF5-4012-000 (pad)	£16.50
Paper feed separation pad assembly (tray 2)	RB2-9960-000 (pad)	£12.75
Paper pickup roller assembly	RG5-6952-000 (paper path)	£21.25
HP Colour LaserJet 1500 / 2500 series	C9700A (black toner)	£52.07
HP Colour LaserJet 1500 / 2500 series	C9701A (cyan toner)	£61.32
HP Colour LaserJet 1500 / 2500 series	C9702A (yellow toner)	£61.32
HP Colour LaserJet 1500 / 2500 series	C9703A (magenta toner)	£61.32
HP Colour LaserJet 1500 / 2500 series	C9704A (drum kit)	£103.91
HP Colour LaserJet 3500/3700 series		
Fuser assembly (HP Colour LaserJet 3500 / 3700 series)	RM1-0430-000 (fuser)	£ call
Transfer roller	RM1-0740-000 (transfer roller)	£ call
Paper feed repair kit (HP LaserJet 3500)	FKITLJ3500 (feed repair kit)	£ call
Paper feed repair kit (HP LaserJet 3700)	FKITLJ3700 (feed repair kit)	£ call
Paper pickup roller	RC1-1535-000 (roller)	£ call
Cassette paper pickup assembly	RM1-0731-000 (paper path)	£ call
Sub roller assembly	RM1-0709-000 (paper path)	£ call
Paper separation pad	RC1-0954-000 (pad)	£6.38
HP Colour LaserJet 3500 / 3700 series	Q2670A (black toner)	£79.65
HP Colour LaserJet 3500 series	Q2671A (cyan toner)	£85.57
HP Colour LaserJet 3500 series	Q2672A (yellow toner)	£85.57
HP Colour LaserJet 3500 series	Q2673A (magenta toner)	£85.57
HP Colour LaserJet 3700 series	Q2681A (cyan toner)	£102.52
HP Colour LaserJet 3700 series	Q2682A (yellow toner)	£102.52
HP Colour LaserJet 3700 series	Q2683A (magenta toner)	£102.52
HP Colour LaserJet 4500/4550 series		
Upper fuser roller	RB2-0501-000 (fuser spare)	£51.79
Lower fuser roller	RB2-0502-000 (fuser spare)	£44.62
Transfer roller assembly	RF5-2112-000 (transfer roller)	£24.00
Paper feed repair kit (HP Colour LaserJet 4500, 4500N, 4550, 4550N) (contains MP tray feed tyre, MP tray feed tyre rear cover roller, 1x MP tray separation pad, 2x cassette feed/separation rollers, 4x half moon tyres and 1x torque clutch)	FKITLJ4500 (feed repair kit)	£33.10
Paper feed repair kit (HP Colour LaserJet 4500DN, 4550DN) (contains MP tray feed tyre, MP tray feed tyre rear cover roller, 1x MP tray separation pad, 4x cassette feed/separation rollers, 8x half moon tyres and 2x torque limiter clutches)	FKITLJ4500D (feed repair kit)	£47.83
Paper pickup roller (tray 1)	RB2-0717-000 (roller)	£8.63
Paper pickup roller (tray 2 - D-shaped, 4x off required)	RB1-8865-000 (roller)	£4.60

Description	Part No.	Unit Cost
Paper pickup roller (tray 2)	RF5-2092-000 (roller)	£17.75
Paper separation roller (tray 2 and 3 - blue core)	RF5-2490-000 (roller)	£4.75
Paper feed separation pad (tray 1)	RB2-0734-000 (pad)	£12.13
HP Colour LaserJet 4500 / 4550 series	C4191A (black toner)	£53.53
HP Colour LaserJet 4500 / 4550 series	C4192A (cyan toner)	£77.17
HP Colour LaserJet 4500 / 4550 series	C4193A (magenta toner)	£77.17
HP Colour LaserJet 4500 / 4550 series	C4194A (yellow toner)	£77.17
HP Colour LaserJet 4500 / 4550 series	C4195A (drum kit)	£52.36
HP Colour LaserJet 4500 / 4550 series	C4196A (transfer kit)	£129.78
HP Colour LaserJet 4500 / 4550 series	C4198A (fuser)	£151.53
HP Colour LaserJet 4600 series		
Paper pickup assembly	RG5-6468-000 (paper path)	£131.01
Paper pickup roller (tray 1) MP tray	RG9-1529-000 (roller)	£14.75
Paper pickup roller (tray 2)	RF5-3739-000 (roller)	£6.25
Separation pad	RF5-3750-000 (pad)	£10.50
HP Colour LaserJet 4600 series	C9720A (black toner)	£92.80
HP Colour LaserJet 4600 series	C9721A (cyan toner)	£125.84
HP Colour LaserJet 4600 series	C9722A (yellow toner)	£125.84
HP Colour LaserJet 4600 series	C9723A (magenta toner)	£125.84
HP Colour LaserJet 4600 series	C9724A (transfer kit)	£162.54
HP Colour LaserJet 4600 series	C9726A (fuser)	£212.99
HP Colour LaserJet 5500 series		
Paper separation pad (tray 1) MP tray	RF5-3865-000 (pad)	£6.25
Paper pickup roller (tray 1) MP tray	RG9-1529-000 (roller)	£14.75
Paper pickup roller	RF5-3340-000 (roller)	£20.75
Paper feed / separation roller (tray 2)	RF5-3338-000 (roller)	£26.00
Paper pickup assembly (tray 2)	RG5-6670-000 (paper path)	£266.08
Paper pickup assembly (tray 3/4)	RG5-6748-000 (paper path)	£177.47
Paper pickup drive assembly	RG5-6661-070 (paper path)	£71.30
HP Colour LaserJet 5500 series	C9730A (black toner)	£135.44
HP Colour LaserJet 5500 series	C9731A (cyan toner)	£192.15
HP Colour LaserJet 5500 series	C9732A (yellow toner)	£192.15
HP Colour LaserJet 5500 series	C9733A (magenta toner)	£192.15
HP Colour LaserJet 5500 series	C9734A (transfer kit)	£123.85
HP Colour LaserJet 5500 series	C9736A (fuser)	£155.28
HP Colour LaserJet 8500/8550 series		
Paper feed repair kit (HP Colour LaserJet 8500, 8500N, 8500DN, 8550, 8550N, 8550DN) (contains MP tray feed tyre, 6x feed rollers and 3x separation rollers)	FKITLJ8500 (feed repair kit)	£35.85
Paper pickup roller (tray 1)	RB1-9526-000 (roller)	£6.50
Paper pickup roller (tray 2, 3 and 4 - 2x off required per tray)	RF5-1834-000 (roller)	£5.50
Paper separation roller (tray 2, 3 and 4 - 1x off required per tray)	RF5-1835-000 (roller)	£6.25
HP Colour LaserJet 8500 / 8550 series	C4149A (black toner)	£70.36
HP Colour LaserJet 8500 / 8550 series	C4150A (cyan toner)	£111.24
HP Colour LaserJet 8500 / 8550 series	C4151A (magenta toner)	£111.24
HP Colour LaserJet 8500 / 8550 series	C4152A (yellow toner)	£111.24
HP Colour LaserJet 8500 / 8550 series	C4153A (drum kit)	£95.18
HP Colour LaserJet 8500 / 8550 series	C4154A (transfer kit)	£244.08
HP Colour LaserJet 8500 / 8550 series	C4156A (fuser)	£196.78
HP Colour LaserJet 9500 series		
Fuser assembly	RG5-6098-000 (fuser)	£ call
Transfer roller assembly	RG5-6178-000 (transfer roller)	£76.08
Secondary transfer roller assembly	RG5-6179-000 (transfer roller)	£246.33
Paper feed repair kit	FKITLJ9500 (feed repair kit)	£ call
Separation pad (tray 1) MP tray	RF5-3490-000 (pad)	£33.00
Paper pickup roller (tray 1) MP tray	RB2-1820-000 (roller)	£28.50
Multi Purpose tray guide pad	RF5-3489-000 (pad)	£20.18

Description	Part No.	Unit Cost
Manual feed pickup assembly	RG5-6090-000 (paper path)	£225.82
Pickup roller	RF5-3340-000 (roller)	£20.50
Paper feed / separation roller (2000 sheet tray) 3x required)	RF5-3338-000 (roller)	£26.18
Torque limiter clutch	RB2-5759-000 (clutch)	£20.18
Vertical registration assembly	RG5-6225-000 (paper path)	£143.92
Paper registration roller assembly	RG5-6016-000 (paper path)	£143.80
HP Colour LaserJet 9500 series	C8550A (black toner)	£97.85
HP Colour LaserJet 9500 series	C8551A (cyan toner)	£199.24
HP Colour LaserJet 9500 series	C8552A (yellow toner)	£199.24
HP Colour LaserJet 9500 series	C8553A (magenta toner)	£199.24
HP Colour LaserJet 9500 series	C8554A (cleaning kit)	£36.92
HP Colour LaserJet 9500 series	C8555A (transfer kit)	£229.05
HP Colour LaserJet 9500 series	C8556A (fuser)	£171.77
HP Colour LaserJet 9500 series	C8560A (black drum)	£190.89
HP Colour LaserJet 9500 series	C8561A (cyan drum)	£297.59
HP Colour LaserJet 9500 series	C8562A (yellow drum)	£297.59
HP Colour LaserJet 9500 series	C8563A (magenta drum)	£297.59